

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Drawer DD

Artesia, NM 882

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0115
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-13978

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Leeman Fed.

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Pecos Slope Abo

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12-T9S-R25E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P.O. Box 730, Roswell, N.M. 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL & 2310' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, CR, etc.)

3685' G.L.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Propose to plug and abandon as follows:

Well Data: 8 5/8" at 958 ft. - cement circulated

4 1/2" at 4491 ft. - TOC at 3200 ft.

One inched between 8 5/8" & 4 1/2" w/150 sx

Perfs: 4370 - 4380 w/45 holes

Set 100 ft plug from 4300 to 4400 ft. inside 4 1/2" Casing and tag plug

Set 100 ft plug from 1675 to 1775 ft. inside 4 1/2" Casing, 1600'-1500'

Set 100 ft plug from 900 to 1000 ft. inside 4 1/2" Casing

Set 10 sx surface plug. Install dry hole marker, clean and level location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

JUL 22 1987

*See Instructions on Reverse Side