

clsF

CONFIDENTIAL INFORMATION

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

5. LEASE DESIGNATION AND SERIAL NO.
NM 27791

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Zane ABS Federal Com

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Pecos Slope Abo

11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA
Unit G, Sec. 15-T9S-R26E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

1. OIL WELL GAS WELL OTHER TITE HOLE - P&A

2. NAME OF OPERATOR
Yates Petroleum Corporation ✓

3. ADDRESS OF OPERATOR
105 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1780' FNL & 1980' FEL

14. PERMIT NO.
API #30-005-62577

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3790' GR

RECEIVED
APR 03 '89
O.C.D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	
(Other) _____		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 5000'. Reached TD 1:15 AM 12-25-87. Received verbal permission to plug well from Shannon Shaw, BLM, Carlsbad, NM.

Plugged well as follows:

- Plug #1 set at 4984' w/35 sxs Class "C" Neat. PD 1:00 AM 12-26-87.
- Plug #2 set at 4433' w/35 sxs Class "C" Neat. PD 1:45 AM 12-26-87.
- Plug #3 set at 1031' w/35 sxs Class "C" Neat. PD 4:45 AM 12-26-87.
- Plug #4 set at 60' w/20 sxs Class "C" Neat. PD 8:15 AM 12-26-87.

Set regulation abandonment marker.

TITE HOLE!

Post ID-2
4-7-89
PFA

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Production Supervisor DATE 12-28-87

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore, Liability under bond is retained until surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
PETER W. CHESTER
DATE
MAR 31 1989
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA