

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
NM Oil & Gas Commission
(Other Instructions on reverse side)
Artesia, NM 88210

BLM Roswell District
Modified Form No.
NM60-3160-4

215F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P&A		5. LEASE DESIGNATION AND SERIAL NO. NM 31633	
2. NAME OF OPERATOR ABO PETROLEUM CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL, Sec. 30-T5S-R24E		8. FARM OR LEASE NAME Pozna Federal	
14. PERMIT NO. API #30-005-62585		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4123.5' GR		10. FIELD AND POOL, OR WILDCAT Und. West Pecos Slope Abo	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit I Sec. 30-5S-24E NMPM	
		12. COUNTY OR PARISH Chaves	
		13. STATE NM	

NOV 21 1989

O.C.D.
ARTESIA, OFFICE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANE	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-20-89. Plugged well as follows: RU. Bled well down. NU BOP. Unset packer. POH. Tally tubing (108 jts 2-3/8"). RIH to 3655' and spot 15 sx Class "C". POOH.
10-23-89. Tagged bottom hole plug at 3537'. Mix 9.5 ppg plugging mud and circulate hole.
10-24-89. Cut off 4 1/2" casing at 2481'. Laid down 60 jts. RIH w/2-3/8" tubing to 2546'. Spot 35 sx cement w/2% CaCl. WOC 3-4 hrs. RIH to tag, did not tag. Respot plug w/35 sx cement. Notified BLM, Roswell, NM. RBIH and tagged plug at 2406'. POOH at 1410'. Spot 60 sacks. WOC. Tagged at 1240'. POOH at 60'. Spot surface plug w/20 sx. Dug out cellar. Cut off wellhead. Installed dry hole marker. Plugging completed 10-26-89.

NOTE: Notified, BLM, Roswell, NM, each day during plugging operations.

18. I hereby certify that the foregoing is true and correct

SIGNED *James D. Suddeth*

TITLE Production Supervisor

DATE 11-6-89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TELE _____
Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

APPROVED
DATE PETER W. CHENTER

NOV 16 1989

*See Instructions on Reverse Side