## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HOY BUTTON CHA YOH:	PAC	
40. 07 CONICO BELLEVED	<u> </u>	
DISTRIBUTION		
SANTA FE		
FILE	K	1
U.S.O.S.		
LAND OFFICE	_	ł
OPERATOR		l

## OIL CONSERVATION DIVISION

40. 47 COPIES ACCEIVES	Р. О. ВОХ	2009	Revised 10-1-79	
DISTRIBUTION				
SANTA FE	SANTA FE, NEW	MEXICO 87301	Sa. Indicate Type of Lease	
FILE			State X Fee	
U.S.G.S.			5. State Oil & Gus Leane No.	
LAND OFFICE	•		LG 939	
OPERATOR	•		The second	
	THE STORES AND DEPORTS ON	WELLS		
SUNDRY	NOTICES AND REPORTS ON TO DEEPEN OR PLUG BA	TILLES		
(DO HOT USE THIS FURN FOR PRICATIO	N FOR PERMIT -" (FORM C-101) FOR SUCH	Photo Po	7. Unit Agreement Name	
1.		L. Serving P. C. V. L.		
OIL WELL X	OTHER-		8. Farm or Lease Hame	
2. Name of Operator		1:01: 04 :00	Witz VN State	
Yates Petroleum Com	Yates Petroleum Corporation V NOV 21 '88		9. Well No.	
J. Address of Operator			2	
105 South 4th St.	Artesia, NM 88210		10, Field and Pool, or Wildcat	
		ARTESIA, OFFICE	l .	
4. Location of Well			Foor Ranch PrePermian	
UNIT LETTER A 60	60 PEET FROM THE North	LINE AND PEET PA	L.L.L.L.L.L.L.L.L.L.L.L.L.L.L.L.L.	
			<i>~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ </i>	
East SECTIO	H 26 TOWNSHIP 9S	HANGE	(!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!	
THE CINC.			12. County	
15. Elevation (Show whether DF, RT, GR, etc.)		Chaves		
	3802.7' G			
1t. Chack	Appropriate Box To Indicate N	lature of Notice, Report or	Other Data	
Cneck 7	appropriate box to mercure	SUBSEQUE	ENT REPORT OF:	
NOTICE OF IN	TENTION TO:		_	
		REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON	<u>—</u>	1		
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB	ing perforationsX	
		OTHER ACTUIZED CATEGO	1foretions	
12	[	Spot sand over lower perforations.		
OTHER		l la series deser inclu	ding estimated date of starting any propose	
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent des	tails, and give pertinent untes, the ta	ding estimated date of starting any propose	
work) SEE RULE 1103.				
•				
Pig un Schlumherge	er and tagged PBTD 6117'.	Spotted 10.5 sacks s	and to fill up	
KIE OF SCHESING - B-	for day to let cand s	ettle. Tagged sand at	6057'. Acidized	

to 6040'. Shut down for day to let sand settle. Tagged sand at 6057 perforations 6012-6039' w/10000 gals 15% NEFE acid. Perforations open in Ordovician: 6012-6039'.

Began work 9-28-88; completed work 10-4-88.

	Information above is true and complete to the beat of my knowledge and belief.  TITLE Production Supervisor	11-18-88
APPROVED BY	Original Signed By  Mike Williams  TITLE	