

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

CISF
OP

Form C-103
Revised 10-1-78

API #30-005-62615

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
L-6772

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A MAY 25 '88	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Whitworth RU State
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. 4
4. Location of Well UNIT LETTER E 2130 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 9S RANGE 26E NMPM.	10. Field and Pool, or Withcat Unders. Four Ranch PrePermian
15. Elevation (Show whether DF, RT, GR, etc.) 3824.2' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission obtained from Darrell Moore, NMOCD, Artesia, NM, by Tim Bussell 5-19-88, to plug well as follows:

- TD 6278'
- Plug #1 6278-6178' w/35 sx Class C. PD 1:30 AM 5-20-88.
- Plug #2 6027-5927' w/35 sx Class C. PD 2:45 AM 5-20-88.
- Plug #3 5306-5206' w/35 sx Class C Neat. PD 3:45 AM 5-20-88.
- Plug #4 4614-4514' w/35 sx Class C Neat. PD 4:45 AM 5-20-88.
- Plug #5 2352-2252' w/50 sx Class C Neat. PD 6:15 AM 5-20-88.
- Plug #6 1185-1085' w/35 sc Class C Neat. PD 7:30 AM 5-20-88.
- Plug #7 Surface w/10 sx. PD 10:00 AM 5-20-88.

Install regulation abandonment marker.

Post FD-2
6-10-88
P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY Johnnie Robinson TITLE Production Supervisor DATE 5-23-88

APPROVED BY Johnnie Robinson TITLE Production Supervisor DATE 3-11-91

CONDITIONS OF APPROVAL, IF ANY: