

APPROVED *Joe R. Smith*
DISTRICT ENGINEER
OCT 14 1948

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 052351
Unit Lucky Lakes Area
1 000. #405

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Report on Accident.....	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Yates-Kimes

Artesia, New Mexico.

Sept. 21, 19 48

Well No. 1 is located 660 ft. from [N] line and 659 ft. from [E] line of sec. 28
NE 1/4 Sec. 28 15 S., 29 E. N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Chaves New Mexico.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On Sept. 2, 1948, while attempting to kill gas flow encountered at 1739 feet, the well caught on fire from Halliburton Oilwell Cementing Co. pump truck exhaust, while mixing mud.

The rig burned down and three men were slightly burned, none critically.

Estimated gas volume, four million feet.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Martin Yates, Jr.

Address Box 397,

Artesia, N. Mex.

By

Title Unit Operator.