Energy, Mine.

State of New Mexico and Natural Resources Department

Form C-103 Revised 1-1-89

## OIL CONSERVATION DIVISION

DISTRICT I	OIL CONSER	VATION DIVIS	ION			
P.O. Box 1980, Hobbs, NM 88241-1980	2040 South Pacheco Santa Fe, New Mexico 87505			WELL API NO. 30-005-00461		
DISTRICT II				5. Indicate Type of Lease		
811 S. First Street, Artesia, NM 88210					STATE X	FEE
DISTRICT III				6. State Oil & Gas Lease No.	-	
1000 Rio Brazos Rd., Aztec, NM 87410				L-729		
SUNDRY NOTICES AND REPORTS ON WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lesse Name or Unit Ague	ment Name	
DIFFERE	NT RESERVOIR USE "APPLICATION FO					
1. Type of Well:	(FORM C-101) FOR SUCH PROPOSA	ы.,		-		
OIL GAS				MULLIS STATE		
WELL WELL OTHER				8 Well No.		
Name of Opestor						
ELK OII	L COMPANY	<del></del>		A-1		
3. Address of Operator	DEFICE BOY OLD BOOME	L NIEVAL BAEVIO	D 00202 0210			
	OFFICE BOX 310. ROSWEL	L, NEVV MEXICO	J 66202-0310			
4. Well Location  Unit Latter D	; 660 Feet From The	WEST	Lime and 660	1	Seet From The	NORTH Line
Urnit Letter					_	
Section 30	Township 15 SOUT	Н	Range 29 EA	ST NMPM	CHAVES	County
Steam		(Show whether DF, RKB, R	T, GR, etc.)			
		3710' GR		1000		
11.	Check Appropriate Bo	ox to Indicate Na				
NOTICE O	F INTENTION TO:			SUBSEQUENT RE	EPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK		ALTERING CASING	
TEMPORABILY ARANDON CHANGE PLANS COMMENCE DRILL				E OPNS	plug and abando	NMENT
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	JOPNs.	7,007,112,111,20	
PULL OR ALTER CASING			CASING TEST AND CE	MENTJOB		
		<del></del> 1				
OTHER:			OTHER:			
12. Describe Proposed or Completed SEE RULE 1103	Operations (Clearly state all pertinent details,	and give pertinent dates, in	cluding estimated date of star	ting any proposed work)	260	
	PLUG AND ABANDON WE	LL AS FOLLOW	IS:	222312	-05/5%	
SEE RULE 1103   INTEND TO PLUG AND ABANDON WELL AS FOLLOWS: (1) Set 100' plug at 1450' to 1350', inside 8 5/8" casing. To G   (2) Set 100' plug at 367' to 267', inside 8 5/8" casing. To G						
(1) Set 100 plug at 1400 to 1600, inside 0 6/0 satisfy. 7/49						
(2) Set 100' plug at 367' to 267', inside 8 5/8" casing. In C						
, ,	' plug at 50' to 0', inside 8 5/	o casing.		RECEIV	ED	
(3) Set 50' plug at 50' to 0', inside 8 5/8" casing.  (4) Install dry hole marker.  (5) Cut off anchors.  (6) Cleanup location.						
(5) Cut off anchors.				15	<del>,</del> ~/	
(6) Cleanu	p location.			13.	367	
				101172	686	
		-: NI				
* Brine	gel between all com	ion Plugs.				
+ NotiFi	E MMOCD TO WITE	ous Placaina	Onprations			
I here by certify that the information abo	C N. MOCD TO with	dge and behaf				
	_		SIDENT		DATE	9/21/00
SIGNATURE		TITLE PRE	OIDENI			
TYPE OR PRINT NAME	JO(SEP)H J. KELLY			TELEPI	HONE NO. 51	05-623-3190
(This space for State Use)						`
(**** space for ottor Ose)	_					<i>i 1</i>
APPROVED BY Mine ST	inellield	TITLE Fiel	O Bep II		DATE 10	12/2000
CONDITIONS OF APPROVAL, IF AN	1Y:		7			