

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

CISF  
Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-005-00461
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. L-729
Lease Name or Unit Agreement Name Mullis State
Well No. A-1
Pool name or Wildcat

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
Name of Operator Elk Oil Company	
Address of Operator PO Box 310 Roswell, New Mexico 88202-0310	
Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>West</u> Line and <u>660</u> Feet From The <u>North</u> Line Section <u>30</u> Township <u>15S</u> Range <u>29E</u> NMPM <u>Chaves</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3710' GR	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/07/01 Tag existing plug @ 2703'. Circulate well with mud laden fluid.

2/07/01 Spot 30 sks of C cement @ 1450'. WOC & Tag @ 1310'

2/07/01 Spot 30 sks of C cement @ 375'. WOC & Tag @ 260'

2/07/01 Spot 15 sks of C cement @ 30'-surface

Cut off wellhead & anchors 3' BGL. Cap well with steel plate. Install dry hole marker.

Location leveled and cleaned. Ready for inspection.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly  
TYPE OR PRINT NAME

TITLE President

DATE 02/21/2001

505-623-3190

TELEPHONE NO

(This space for State Use)

APPROVED BY

Phil Hawkins

TITLE

Field Rep I

DATE

4/4/2001

CONDITIONS OF APPROVAL IF ANY