

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

Plug and Abandon

FEB - 8 1994

2. Name of Operator

McCLELLAN OIL CORPORATION

3. Address and Telephone No.

P O DRAWER 730, ROSWELL, NM 88202-0730 (505) 622-3200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 660' FWL Sec. 13-T15S-R29E, N.M.P.M.

5. Lease Designation and Serial No.

NM-31257

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Lisa Fed. "B" No. 1

9. API Well No.

30-005-10430

10. Field and Pool, or Exploratory Area

Double L Queen (Associated)

11. County or Parish, State

Chaves, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other

Plug & Abandon

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-1/2" Csg at 2060' w/250 sx
TOC at 300'
Perfs 1959' - 1970'

2-3/8" EVE tbg.
Top Salt at 470'
Bottom salt at 1200'

1. Set CIBP at 1900' and put 35' cement on top.
2. Load hole with heavy gelled H₂O.
3. 1st plug 1120' - 1020' 30 sx
- 2nd plug 475' - 375' 30 sx Inside 5-1/2" (tag)
- 3rd plug 60' to surface 15 sx
- 4th plug 60' to surface 20 sx between 5-1/2" casing and surface

Clean location and install dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed

Mark McClellan

Title President

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

FEB 2 1994