Form 3160-5 (August 1999)

## **UINI FED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

011121314151613

DRM APPROVED OMB No. 1004-0135 Expires November 30, 2000

NM17114

If Indian, Allottee or Tribe Name

## Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. RECEIVED SUBMIT IN TRIPLICATE - Other instructions on reverse side If Unit or CA/Agreement, Name and/or No. #8910160560 Double L Qn Ut Tract 1 Type of Well ☐ Oil Well ☐ Gas Well ☒ Other Well Name and No. Name of Operator Double L Queen No 7 Saga Petroleum LLC / API Well No. 3a. Address 30-005-20385 3b. Phone No. (include area code) 415 W Wall, Suite 1900, Midland, TX 79701 (915)684-4293 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Double L Queen 1650' FNL & 990 FWĽ 11. County or Parish, State Sec. 18 (E), T15S, R30E Chaves NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen ☐ Production (Start/ Resume) Notice of Intent Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity ☐ Subsequent Report Casing Repair **New Construction** Recomplete Other Change Plans Plug and Abandon Temporarily Abandon ☐ Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Intent to P&A this SI WIW, will notify OCD 24 hrs prior to start operations MIRU, POOH w/rods, NU BOP, POOH w/tbg (5-1/2" csg @ 2025' Perfs 2009'-2019') 4 150 (cm). Set CIBP @ 1930' w/35' cmt on top RIH, circ well w/9.8# mud POOH to 1300', spot 100' cmt plug Perforate 51/2"(5/2) 1300', squeeze 100' cmt Plug Insidera Cut side 51/2"(5/5) - TAG POOH to 4000', spot 100' cmt plug (8-5/8" @ 308"), WOC & tag Perforate 51/2"(5/5) 358 - Squeeze 100' centent Plug, POOH to 30', circ cmt to surface Cut off WH, install dry hole marker Inside 4 Out side 51/2"(5/5) TAG Rectorate 5/2" copo so'. Circulate cement to surface. Inside a Outside 5/2" csg. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Bonnie Husband **Production Analyst** Date 01/11/2001 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.