

OIL CONSERVATION DIVISION DISTRICT II ARTESIA 811 S. FIRST ST. ARTESIA, NM 88210 (505) 748-1283 FAX (505) 748-9720

Jennifer A. Salisbury CABINET SECRETARY			. 111	ne 1, 2000			
Oxy USA, Inc							
P.O. Box 50250							
Midland, TX 79710-0250							
Re	::	Plug	gging Reports	Lease	Well No.	Ut S-T-R	
Form C-103 Report of Plugging for your Oxy Sosa State #1 K-12-17-27 cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been done and location is ready for final inspection.							
()	1.	All pits have been filled ar	nd leveled.			
()	2.	Rat hole and cellar have bee	ar have been filled and leveled.			
()	3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)					
()	4.	The location has been leveled ground contour and has been	been leveled as nearly as possible to original top nd has been cleared of all junk and equipment.			
()	5.	The dead men and tie downs h	tie downs have been cut and removed.			
()	6.	If a one well lease or last burn pit locations have been	remaining well on leveled and cle	n lease, the ared of all j	battery and unk & equipment	
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.							
When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.							
I certify that the above work has been done and the above mentioned lease is ready for OCD inspection and approval.							
					mik Stubble)	
Nar	ne				Mike Stubbl	erield	
Title Field Rep II						.1	