Form 9-331 (May 1963)	DEPAR	UNITED STATES	SUBMIT 1 (Other in Verse side)	I IPLICATES	Form approved, Budget Bureau No. 42-R1424  5. LEASE DESIGNATION AND SERIAL NO.	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)					USA 0559078 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS OTHER					7. UNIT AGREEMENT NAME	
Humble Oil & Refining Co.					8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR					Humble Yates Federal	
Box 1600, Midland, Texas						
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface					10. FIELD AND POOL, OR WILDCAT	
Unit K 1837 FS&WL					Wildcat  11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA	
					S26,T15S,R18E	
14. PERMIT NO.		15. ELEVATIONS (Show when	her DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE	
		to be supplied		GR.	Chaves NM	
16.	Check A	ppropriate Box To Indica	ate Nature of Notic	e. Report, or (	Other Data	
	NOTICE OF INTE		1		CENT REPORT OF:	
TEST WATER SHUT-	OFF	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SH	TREATMENT	REPAIRING WELL ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*	1	OR ACIDIZING	ABANDONMENT*	
REPAIR WELL (Other)	<u></u>	CHANGE PLANS	(Other) _ (Non-	rE: Report results	s of multiple completion on Well eletion Report and Log form.)	
17. DESCRIBE PROPOSED of proposed work. I nent to this work.	R COMPLETED OF well is direct	PERATIONS (Clearly state all perionally drilled, give subsurface	tinent details, and give locations and measure	e pertinent dates ed and true vertic	including estimated date of starting any all depths for all markers and zones perti-	
w/12.5# Gilson sx ditto. Set OC pkr set @ : and recovered Set plug #5 fr 36 sx below pl swedge & valve	nite & 1/2 plug #3 f 2780' w/50 same. Le c 1020-112 cr. Set p e on top.	2# floseal & 2% ca fr 2730-2830 w/14 D' cmt above & 50' eft 420' 7" csg in 20' w/72 sx ditto	chl per sack, sx ditto. Plu below pkr. ( hole. Set pl using a DC pkr ' w/5 sx ditto le marker. Wi	Set plug ug placed i Cut off 7" Lug #4 fr l r w/1050' w o inside 8-	w/60 sx portland cmt #2 fr 4200-4300 w/43 in 7" csg using HOWCO csg @2360' and pulled .500-1600' w/42 sx ditto. #/36 sx cmt above & .5/8" csg. Placed your office when	
File & hold from the US	until w GS.	e get approved		1 V E D		

TITLE .

Agent

DATE

18. I hereby certify that the foregoing strue and correct

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY: