

(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

(Other instructions on reverse side)

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

|  |  |   |                         |
|--|--|---|-------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole  |  | 5. LEASE DESIGNATION AND SERIAL NO.<br>NM-067667                    |                         |
| 2. NAME OF OPERATOR<br>Charles B. Read   |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME<br>--                          |                         |
| 3. ADDRESS OF OPERATOR<br>P. O. Box 2126, Roswell, New Mexico 88201  |  | 7. UNIT AGREEMENT NAME<br>--  |                         |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><br>990' FSL & 990' FEL |  | 8. FARM OR LEASE NAME<br>Barnhill-Federal                           |                         |
| 14. PERMIT NO.   |  | 9. WELL NO.<br>1  |                         |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>3443' KB   |  | 10. FIELD AND POOL, OR WILDCAT<br>Unders<br>Buffalo Valley Gas Penn |                         |
|  |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>3-15S-27E       |                         |
|  |  | 12. COUNTY OR PARISH<br>Chaves                                      | 13. STATE<br>New Mexico |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated dates, starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Set cmt plugs as follows:

|       |            |
|-------|------------|
| 30 SX | 7406-7506' |
| 30 SX | 5913-6013' |
| 30 SX | 4099-4199' |
| 30 SX | 2650-2750' |
| 50 SX | 1150-1250' |
| 50 SX | 305- 405'  |
| 25 SX | 0- 20'     |

Cut &amp; removed 8 5/8" csg. @ 1211'.

Plugged and Abandoned 7/12/68.

The Dry Hole Marker has been erected, the location cleaned and leveled and is ready for inspection.

RECEIVED  
DEC 30 1968  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

RECEIVED  
DEC 27 1968

DEC 27 1968

O. C. C.  
ARTESIA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE Dec. 26, 1968

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

FEB 1 1969  
R. L. BECKMA

\*See Instructions on Reverse Side