

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-005-60078

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Double L Queen Unit Tract 22
Fed Agree 8910160560

8. Well No. 1

9. Pool name or Wildcat
Double L Queen

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3851' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other WIW ☐

2. Name of Operator
Saga Petroleum LLC

3. Address of Operator
415 W Wall, Suite 1900
Midland, TX 79701

4. Well Location
Unit Letter A : 330 feet from the N line and 330 feet from the E line
Section 1 Township 15S Range 29E NMPM County CHAVES

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | MULTIPLE COMPLETION <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |
| OTHER: <input type="checkbox"/> | | OTHER: <input type="checkbox"/> | |

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

Intent to P&A this SI WIW

MIRU, POOH w/rods, NU BOP, POOH w/tbg (5-1/2" csg @ 1980' w/250 sx)

Set CIBP @ 1950' w/35' cmt on top Set CIBP @ 1880' w/35' cement to top.

RIH, circ well w/9.8# mud

POOH to 1300', spot 100' cmt plug, perf 5-1/2" csg @ 1300', squeeze 100' cmt plug inside & outside 5-1/2" csg, tag

POOH to 290', spot 100' cmt plug - perf & squeeze @ 290' - fill annulus w/cmt - tag plug

(8-5/8" csg @ 296' w/260 sx)

Perf 5-1/2" csg @ 50', circ cmt to surface

Cut off WH, install dry hole marker

* Brine Gel between all cement plugs.

. Notific N.M.O.C.D. to witness plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bonnie Husband

TITLE Production Analyst

DATE 03/23/2001

Type or print name Bonnie Husband

Telephone No. (915)684-4293

(This space for State use)

APPROVED BY

Steve Sheffield

TITLE Envir. Eng. Spec. I

DATE 2/23/2001

Conditions of approval, if any: