4.

16.

U FED STATES SUBMIT IN TRL. SATE* DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Budget Bureau No. 42

	rc 069880-7	
SUNDRY (Do not use this form Use	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OUL GAS WELL	OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
JACK L.	McClfllan 1	LISA "A" FEDERAL
3. ADDRESS OF OPERATOR	848, Roswell, New Mexico 88201	9. WELL NO.
 LOCATION OF WELL (Report See also space 17 below.) At surface 	location clearly and in accordance with any State requirements.	10. FIELD AND FOOL, OR WILDCAT SULIMAR QUEEN
1650' FSL	& 660' FWL	SEC. 24-T 15S-R29E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

39481 G.L.

NOTICE OF INTENTION TO:		SUBSEQUENT	SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of Completion or Recompletion	ALTERING CASING ABANDONMENT* Multiple completion on Well n Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

ON 12/14/71 RAN HALLIBURTON R-4 PKR. ON 2 3/8" O.D. EUE TBG.

PKR. SET AT 1951' WITH 10,000# TENSION. ANNULUS LOADED WITH

FORMATION WATER TREATED FOR SCALE AND CORROSION.

PLAN TO START INJECTION 12/30/71.

RECEIVED

JAN 1 0 1972

O. C. 3 ARTESIA. C

CHAVES

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE PRODUCTION SUPT.	DATE 12/28/71
(This space for Federal or State office use)	TITLE	DATE
CONTROL OF APPROVAL, IF ANY:		1644 k 4,61

*See Instructions on Reverse Side