

15F  
up

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

NOV 12 1992

O. C. D.  
ARTESIA - 2088

WELL API NO. 30-005-60090
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-729
7. Lease Name or Unit Agreement Name J.W. State
8. Well No. 1
9. Pool name or Wildcat Round Tank Queen (Assoc)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3710' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Elk Oil Company
3. Address of Operator P.O. Box 310 Roswell, NM 88202-0310
4. Well Location Unit Letter K : 1677 Feet From The West Line and 2300 Feet From The South Line Section 30 Township 15 South Range 29 East NMJM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-4-92 Spot 50 sxs @ 1525' - tag 1470'  
8-5-92 Spot 10 sxs @ 1470' - 1370'  
8-5-92 Spot 25 sxs @ 600' - 400'  
8-5-92 Perforate @ 370' - circulate 65 sxs cement to surface  
Leave casing full

Circulated 10# mud.  
Installed dry hole marker.

Location cleaned and ready for inspection.

Post ID-2  
12-4-92  
P & H

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly TITLE President DATE 11/10/92  
TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. 505/623-3190

(This space for State Use)

ORIGINAL SIGNED BY RAY SMITH  
FIELD REP. II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: