

2 5/8" e3131 - circ
1 7/8" - 5 1/2" e2020 w/300 SX
2" w/ pkr e1900'

Salt 350-1120

Need to verify cmt behind
5 1/2" CSG

Make sure cmt plug
@ BX + TX inside
+ outside 5 1/2"

<sup>CIBP
OR</sup> LB 9-27-84
Perm pkr @ 1875 w/25 SX
TOC 5 1/2" @ 680^{on top.}

By CBL. Spot
25 SX @ 1170-1070
Perf. @ 335 & spot cmt
Fm. 335-235, run 1 jt & circ