

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
MM 0493370A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Snyder Federal9. WELL NO.
310. FIELD AND POOL, OR WILDCAT
Sulimar Queen11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 26-T15S-R29E**

12. COUNTY OR PARISH 13. STATE

Chaves**New Mexico**1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER **Dry Hole**2. NAME OF OPERATOR
Cities Service Oil Company3. ADDRESS OF OPERATOR
Box 69 - Hobbs, New Mexico 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface **1980' FSL & 1980' FEL of****Sec. 26-T15S-R29E Chaves County, New Mexico**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2915 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 1997 Lime. Plugged and Abandoned. This well was plugged and abandoned in the following manner:

1. Loaded hole with mud laden fluid.
2. Displaced a 35 sack cement plug @ 1995-1885.
3. Displaced a 35 sack cement plug @ 1260-1150 (Base of Salt 1210).
4. Displaced a 35 sack cement plug @ 430-375 (1/2 in and 1/2 out of 3 5/8" casing. Set and cemented @ 421 w/175 sacks.
5. Set a 10 sack cement surface plug @ 30-0 w/4" pipe extending 4' above the surface to designate a P & A location.

RECEIVED**JUL 27 1970****U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO****RECEIVED****AUG 13 1970**

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*TITLE **District Manager****U. S. G. C.**
DATE **07/28/70**

(This space for Federal or State office use)

TITLE _____

DATE _____

APPROVED
CONDITIONS OF APPROVAL, IF ANY:**APPROVED****R. L. BEEKMA**

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.