			ick.	
Submit 3 Copies To Appropriate District State Office	of New Mexic	20	(1) D	Form C-103
District 1 dinergy, Miner	anergy, Minerals and Natural Resources		THE LANGE	Revised March 25, 1999
1625 N. Franch Dr., Hobbs, NM 87240 District fi			WELL API NO.	30-005-60161
811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION		5. Indicate Type	of Lease	
District III 2040 South Pacheco 1000 Rio Brazos Rd., Azieu, NM 87410		STATE 2		
District IV Santa Fe, NM 87505		6. State Oil & C		
2040 South Pacheco, Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Double L Queen Unit Tract 18	
PROPOSALS.) I. Type of Well:			Fed Agree 89101	160560
Oil Well Gas Well OtherWIW				
2. Name of Operator Saga Petroleum LLC			8. Well No. 3	
3. Address of Operator 415 W Wall, Suite 1900			9. Pool name or Wildcat	
Midland, TX 79701			Double L Queen	
4. Well Location				
Unit Letter C • 990 feet from the N line and 1650 feet from the W line				
Only Letter C 220 feet from the 10 fine and 1030 feet from the W fine				
Section 25 Townshi	p15S R	ange 29E	NMPM	County CHAVES
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
11. Check Appropriate Box to	Indiate N	Ob C	Panort or Other	Doto
NOTICE OF INTENTION TO:	mulcate 14		SEQUENT RE	
PERFORM REMEDIAL WORK PLUG AND ABAN	DON 🔀	REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING MULTIPLE COMPLETION		CASING TEST AND CEMENT JOBS	ND 🗀	ABANDONMEN
	,,			
OTHER:		OTHER:		معداد المعمسندي وسنادوا
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion				
or recompletion.				
Intent to P&A this SI WIW				
MIRU, POOH w/rods, NU BOP, POOH w/tbg (4-1/2" 9.5# csg @ 1962' w/200 sx)				
Set CIBP @ 1950' w/35' cmt on top (IBP set 2 1850, w/35' content on Top. RIH, circ well w/9.8# mmd				
POOH to 1300', spot 100' cmt plug, perf 5-1/2" csg @ 1300', squeeze 100' cmt plug inside & outside 5-1/2" csg, tag				
POOH to 390', spot 100' cmt plug - perf & squeeze @ 392' - fill annulus w/cmt - tag plug				
(8-5/8" 24# csg @ 353' w/275 sx) Perf 5-1/2" csg @ 50', circ cmt to surface			189 10 100	
Cut off WH, install dry hole marker			(45°) 1	*
		/	ω, ". 	
		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	$oldsymbol{\hat{\lambda}}_{i} = oldsymbol{\hat{\gamma}}_{i+1}^{-1} oldsymbol{\hat{\gamma}}_{i+1}^{-1}$	
			OCHECE/III	•
		/:	OCD - ARY	
Notific N.M.O.C.D. To witness Procent Operations.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Bonnie Bushano	TITLE	Production Analyst		DATE 03/23/2001
Type or print nameBonnie Husband			Tele	phone No. (915)684-4293
(This space for State use)				
``				
* DDD/3//ED BV	<i>-</i>	F F . C.	. T	DATE 2/20/2001
APPROVED BY The Stall of Approval, if any:	TITLE	Envil. Eng. Spe	,. T	DATE 2/20/2001.