

Submit 3 Copies
to Appropriate
District Offices

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.
30-005-60168

5. Indicate Type of Lease
STATE ☐ FEE ☐

6. State Oil & Gas Lease No.
FED NM0199827A

7. Lease Name or Unit Agreement Name
Double L Queen Unit

8. Well No.
1

9. Pool name or Wildcat
Double L Queen

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3796

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER WIW

2. Name of Operator
Saga Petroleum LLC

3. Address of Operator
415 W. Wall, Suite 1900, Midland, TX 79701

4. Well Location
Unit Letter P : 990 Feet From The South Line and 330 Feet From The East Line
Section 23 Township 15S Range 30E 2-3 NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3796

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Intent to P & A this SI WIW - will notify OCD 24 hrs prior to start operation
MIRU, POOH w/rods, NU BOP, POOH w/tbg (4-1/2" csg @ 1926' w/200 sx Perfs 1864-77")
Set CIBP @ 1814' w/35' cmt on top
RIH, circ well w/9.8# mud
POOH to 1300', spot 100' cmt plug
POOH to 392', spot 100' cmt plug (8-5/8" @ 342' w/275 sx), WOC & tag
POOH to 30', circulate cmt to surface
cut off WH, install dry hole marker

Federal Agreement NMNM 070934A Well is #1 in Tract 12



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 10/20/2000

TYPE OR PRINT NAME Bonnie Husband TELEPHONE NO. (915)684-4393

(This space for State Use)

APPROVED BY Federal Well TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: