

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN LICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Re-entry		5. LEASE DESIGNATION AND SERIAL NO. 0559185
2. NAME OF OPERATOR Read & Stevens, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----
3. ADDRESS OF OPERATOR P.O. Box 2126, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME -----
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL & 2310' FEL		8. FARM OR LEASE NAME USA
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) Unknown		10. FIELD AND POOL, OR WILDCAT Lucky Lake
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 15-15S-29E
		12. COUNTY OR PARISH Chaves
		13. STATE N.Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-07-72 Pull rods and pump. Pull tubing. Strip off heads.

2-08-72 Set Bridge plug @ 1841', capped w/10 sx. cement.
Plug inside of 5½" casing 1841' to 1761'
Fill hole with Good mud
Cut and remove 5½" casing @ 1312'
Set 35 sx. cement plug 1342' to 1242'
Set 35 sx. cement plug 350' to 250'
Set 10 sx. cement plug 10' to 0'
Install regulation marker

Will notify when location is ready for inspection.

RECEIVED

FEB 10 1972

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 2-09-72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

DATE



*See Instructions on Reverse Side

MAY 9 1972

O. C. C.
ARTESIA, OFFICE