

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
Artesia, NM 88008

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

JUN 25 1982

2. NAME OF OPERATOR  
McClellan Oil Corporation

O. C. D.  
ARTESIA, OFFICE

3. ADDRESS OF OPERATOR  
P.O. Drawer 730, Roswell, NM

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 1980' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☒

(other)

5. LEASE

NM-27800

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jack Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29-T15S-R29E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

14. API NO.


15. ELEVATIONS (SHOW DF, KDB, AND WD)

3780 G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to P&A as follows: Set 100' plug @ T.D. 100' plug over stub of 4 1/2" csg. 100' plug over base of 8-5/8" csg. (265-365) & 15 sx plug @ surface. Heavy mud between plugs. Set dry hole marker & restore surface as near as possible to its original condition.



OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Joe J. McClellan*

TITLE Operator

DATE

6-22-82

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED AS AMENDED

JUN 24 1982

*Bob*  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR



# United States Department of the Interior

## MINERALS MANAGEMENT SERVICE

ROSWELL DISTRICT OFFICE

POST OFFICE DRAWER 1857

ROSWELL, NEW MEXICO 88201

Re: Permanent Abandonment

Well: No. 1 Jack Federal

### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Roswell office is to be notified in sufficient time for a representative to witness all plugging operations.

Roswell Office: (505) 624-1790  
Artesia Sub-District: (505) 746-9838  
Hobbs Sub-District: (505) 393-3612

3. Blowout prevention equipment is required.

#### 4a. Federal Owned Surface:

- a. ☒ In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. Please contact the Bureau of Land Management for the surface restoration requirements for this well at:

Roswell (505) 622-7670  
Carlsbad (505) 887-6544

- b. ☐ Non-Federal Owned Surface:

Surface restoration after abandonment is to be in accordance with the operator-surface owner agreement. When surface restoration is accomplished, please furnish this office with a statement signed by the surface owner that the restoration is to his satisfaction.

5. The plug proposed to be set at T.D. shall be set at 1672' to 1572'.

6. The stub will be set 50' in and 50' of the stub and will be tagged.