				Dil Cons. Commissio Aur DD	n	5F
Form 9-331 (May 1963) 128	7 DEPA	UNITED STATE	S Acrit NTERIC	Con Jud Sisubart In ChipLicati (Other instructions on in verse side) RECEIVED BY	Form approv Budget Bure 5. LEASE DESIGNATION NM 16114	au No. 42-R1424.
(Do not u		NOTICES AND REPO proposals to drill or to deeper PLICATION FOR PERMIT-"		N - WELLS	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME
	GAS OTH	HER Plugged & Aban	doned We	O. C. D.	7. UNIT AGREEMENT N	AME
2. NAME OF OPER.	ATOR	8. FARM OR LEASE NA	8. FARM OR LEASE NAME			
Wood & L	ocker, Inc	Federal "B"	Federal "B"			
3. ADDRESS OF OF	ERATOR	9. WELL NO.	9. WELL NO.			
505 N. B	ig Spring,	1	1			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)					10. FIELD AND POOL, C	DE WILDCAT
At surface	,	Und. Double I	Und. Double L. Queen Assoc			
	ter P loca:		11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA			
the East	line of S	Sec. 3, 1	Sec. 3, T-15-S,			
					R-29-	
14. PERMIT NO.		15. ELEVATIONS (Show	whether DF, R	T, GR, etc.)	12. COUNTY OR PARISI	H 13. STATE
Approved	1 11-21-73	3852' GR			Chaves	NM
16.	Chec	k Appropriate Box To In	dicate Na	ture of Notice, Report, or	Other Data	
NOTICE OF INTENTION TO: SUBSEQU					EQUENT REPORT OF:	
TEST WATER	SHUT-OFF	PULL OR ALTER CASING		WATEB SHUT-OFF	REPAIRING	WELL
FRACTURE TRE	EAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING O	ASING
SHOOT OR ACI	DIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONME	NT*
REPAIR WELL	REPAIR WELL CHANGE PLANS			(Other) <u>Re-plug & abandon</u> X		
(Other)	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)					
17. DESCRIBE PROP proposed we nent to this	OSED OR COMPLETE ork. If well is d work.)*	ED OPERATIONS (Clearly state a directionally drilled, give subsu	ll pertinent rface locatio	details, and give pertinent dat ns and measured and true ver		
4-29-87	Moved in	and rigged up Cha	se Well	Service double der	rrick pulling ur	vit Rig No. 1/
4-30-87				ter w/ 10" by 6" 90 $($		
	HELCO rev	verse unit. Picke	d up 7-	7/8" bit and drille	ed out cement pl	ug at top of
				culate to top of co		
				irculate and rotate		
)' to top of $4\frac{1}{2}$ cas		
				and shut down for	8	

5- 1-87 Pulled out of hole with bit and drill collars and laid down drill collars. Ran 7-7/8" bit, crossover sub and 33 joints of 2-3/8", 5.95#, P-110, PH-6 Hydril used tubing to 965'. Rigged up Halliburton. Mixed and pumped 250 sacks Class "C" cement blended with 2% calcium chloride. Mixed and pumped 220 sacks Class "C" cement and mixed 2% calcium chloride in mixing water. The 8-5/8" casing and 2-3/8' tubing stood full of cement. Mixed and pumped 5 sacks of Class "C" cement and spotted on outside of 8-5/8" casing in cellar. Wait on cement 1 hour. Removed blow-out preventer and cut off 8-5/8" nipple at the 8-5/8" surface casing collar. Cut off 5' of 2-3/8" tubing down inside 8-5/8" collar. Welded on ½" steel plate to 8-5/8" collar and welded on old dry hole marker. Cut off pulling unit anchors and cleaned up location. Released pulling unit. (Plugging witnessed by Peter Chester with BLM from Roswell.)

18. I hereby certify that the foregoing is true SIGNED D. N	and correct 1. Johnson 1. Johnson	DATE 5-4-87	
(This space for Federal or state office use)) TITLE	APPROVED PETER W. CHESTER	
CONDITIONS OF APPROVAL, IF ANY :		JUL 2 8 1987	
	*See Instructions on Reverse Side	BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA	