

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	/
LAND OFFICE	
OPERATOR	/

JUL 6 1982

O. C. D.

5a. Indicate Type of Lease
State <input type="checkbox"/> For <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
NM 115465 A

SUNDRY NOTICES AND REPORTS ON WELLS, ARTESIA, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator DEPCO, INC.	8. Farm or Lease Name DERRICK
3. Address of Operator 800 CENTRAL, ODESSA, TX 79761	9. Well No. 1
4. Location of Well UNIT LETTER G, 1325 FEET FROM THE North LINE AND 1325 FEET FROM East THE LINE, SECTION 3 TOWNSHIP 15-S RANGE 27-E NMPM.	10. Field and Pool, or Wildcat Buffalo Valley Penn
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

We plan to plug the well as follows:

Set CIBP @ 7960-top of perms 7967'.
 Set 150' plug from 7810-7960'.
 Cut off 4 1/2" pipe @ 7100', TOC 7200'.
 Set 150' plug from 7025-7175'. + tag
 Set 150' plug from 5925-6075', WOLF CAMP Top 6000'.
 Set 100' plug from 4044-4144', TUBB top 4094'.
 Set 100' plug from 1510-1610', 8 5/8" depth 1560'. + tag
 Cut off 8 5/8" pipe @ 550'. TOC 610'.
 Set 100' plug from 500' to 600'. + tag
 Set 10 sx. plug @ surface w/dry hole marker.

13

Load hole w/mud

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Denney R. L. Denney TITLE Chief Production Clerk DATE July 2, 1982APPROVED BY W. A. Gussett TITLE SUPERVISOR, DISTRICT II DATE JUL 8 1982

CONDITIONS OF APPROVAL, IF ANY:

Set a 100' Plug from 2590-2690
 + as noted above. 310-410

Notify N.M.C.O.D. in sufficient time to witness

Plugging