7. OF COPIES RECEIVED		<u>_</u>	**	Form C-103
DISTRIBUTION			RECEIVLD	Supersedes Old
SANTA FE		NEW MEXICO OUL CONS	SERVATION COMMISSION	C-102 and C-103
	1 1	- WEN MEXICO OIL CONS	PERTATION COMMISSION	Effective 1-1-65
FI. E	1 1	↓ `• •	MAR 1 0 1976	
U.S.G.S.	l .l		MAN I U 13/0	5a. Indicate Type of Lease
LAND OFFICE		1		State X Fee
OPERATOR	+	1		5, State Oil & Gas Lease No.
OPERATOR]	o. c. c.	
			ARTESIA, OFFICE	L-1894-1
	SHINDE	RY NOTICES AND REPORTS ON	WELLS	
(DO NOT USE THIS FO	DRM FOR PRO	OPOSALS TO DRILL OR TO DEEPEN OR PLUG I	SACK TO A DIFFERENT RESERVOIR.	
	MAPPLICAT	TION FOR PERMIT -** (FORM C-101) FOR SUC	H PROPOSALS.)	
1. OIL TYT GAS				7. Unit Agreement Name
WELL X GAS		OTHER-		
2. Name of Operator				8. Farm or Lease Name
Read & Ste				
	V CIII)	IIIC.		Lucky Lake
3. Address of Operator				9. Well No.
P. O. Box	2			
4. Location of Well				
4. Location of well				10. Field and Pool, or Wildcat
UNIT LETTED AT	2.7	310 FEET FROM THE West	660	Undesignated-Queen
DATE LETTER		PEET FROM THE NOSC	LINE AND FEET	minimum Most
Courth		16 15 6		
THE SOUTH	LINE, SECTI	township 15-Sc	outh RANGE 29-East	MPM. (())
}				
	111111	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	(/////			
	711177.	3824.5' GR-382	26 ' DF	Chaves ()
16.	Check	Appropriate Box To Indicate N	lature of Notice Pepert of	Other Date
NOTI	CE OF IN	NTENTION TO:	SUBSEQU	ENT REPORT OF:
PERFORM REMEDIAL WORK	7	PLUG AND ABANDON	REMEDIAL WORK	
7	╡	LEGG WILD VENERAL .		ALTERING CASING
TEMPORARILY ABANDON	ᆜ		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	J	CHANGE PLANS	CASING TEST AND CEMENT JOB	
			OTHER Perforate	and Treat X
		[7]		<u> </u>
OTHER			-	
10 5		(6) 1 1 1 1 1	1.7	
work) SEE RULE 1103.	ompleted Op	perations (Clearly state all pertinent det	ails, and give pertinent dates, incli	iding estimated date of starting any proposed
20.00, 222 11001			•	
TD 1800' ar	ahv. O	n 3-4-76, perf. 173	8! - 1748! w/2 ist s	shots per foot total
TD 1800' anhy. On 3-4-76, perf. 1738'-1748' w/2 jet shots per foot, total of 20 holes. Acidize w/500 gals. 15% N.E. acid. Formation broke @ 1800#				
or zo note	S. AC	cidize W/500 gais. I	5% N.E. acid. For	mation broke @ 1800#
average treat. press. 1000#, aver. inj. rate 1.75 BPM. ISDP 800#, 5 min.				
STD 400#	10 mir	o STD 300# Swabbo	d hala dry's rea	' \ ' =
DIE 400#,	TO INTI	n. SIP 300#. Swabbe	a note ary & rec.	acid water. Shut-in
overnight. On 3-5-76, SITP 200#. Swab & rec. 200' acid water w/slight				
amount oil. Pulled tubg. & fraced down 4 1/2" csg. w/20,000 gals. 40#				
colled table 2 42 00% of 11ded down 4 1/2 csg. w/20,000 gais. 40#				
gelled water & 40,000# 20/40 sand w/200# adamite & 25 gals. marflo. Max.				
treat. press. 2800#, aver. treat. press. 2700#, aver. inj rate 31 BPM				
ISDP 1200#	#. 15	min. SIP 1150#, tota	al load 500 bblc	Chut in annual late
2002 2000,	1 7 23	min. Dir iibom, coce	it toad 500 bbis.	Shut-in overnight.
			•	
			•	
18. I hereby certify that the	information	above is true and complete to the best	of my knowledge and belief.	
\cap $A : A$	100	\sim \sim		
Ja 11. V	/ 1. //-		•	
SIGNED Law Mil	MISE	rough TITLE A	gent	DATE 3-5-76
		u		
	ور ر	,		
1,1/1	' _ U	and XI	UDEDIUCAD DICTORATE	.₄MAR 1 1 1976
APPROVED BY	XYU	TITLE SI	UPERVISOR, DISTRICT II	0445UI T T 1210

CONDITIONS OF APPROVAL, IF ANY: