

N. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 3 1977

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
L-651 & L-1510

7. Unit Agreement Name

8. Farm or Lease Name
Sanders-State

9. Well No.
1

10. Field and Pool, or Wildcat
Undesignated-Atoka

12. County
Chaves

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- **Dry Hole**

2. Name of Operator **Read & Stevens, Inc.**

3. Address of Operator
P.O. Box 2126, Roswell, New Mexico 88201

4. Location of Well
UNIT LETTER **O**, **660** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **36** TOWNSHIP **15-S** RANGE **26-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3451.4' GR-3463' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8295'. Drilled 7 7/8" hole from 1450' to 8295' RKB. On 6-28-77, received verbal permission from Mr. W.A.Gressett, N.M.O.C.C., Artesia, N.M. to plug and abandon as follows:

1. Set 40 sx. cement plug 7900'-7800'.
2. Set 40 sx. cement plug 6700'-6600'.
3. Set 40 sx. cement plug 5800'-5700'.
4. Set 40 sx. cement plug 4725'-4625'.
5. Set 40 sx. cement plug 2650'-2550'.
6. Set 40 sx. cement plug 1500'-1400'.
7. Set 10 sx. cement plug 10'-surface.
8. Install regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John P. Anderson Jr.* TITLE Agent DATE 9-28-77

APPROVED BY *W. A. Gressett* TITLE SUPERVISOR, DISTRICT II DATE OCT 4 1977

CONDITIONS OF APPROVAL, IF ANY: