

## HALLIBURTON DIVISION LABORATORY

## HALLIBURTON SERVICES

## ARTESIA DISTRICT

## LABORATORY REPORT

No. W612-90TO DeKalb EnergyDate October 26, 1990P. O. Box 1302Artesia, NM 88210

This report is the property of Halliburton Services and neither it nor any part thereof, nor a copy thereof, is to be published or disclosed without first securing the express written approval of laboratory management. It may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Services.

Submitted by \_\_\_\_\_ Date Rec. October 25, 1990Well No. R & S Federal #1 Depth \_\_\_\_\_ Formation \_\_\_\_\_Field \_\_\_\_\_ County \_\_\_\_\_ Source Production TankResistivity ..... 0.110 @ 70°Specific Gravity .. 1.0498 @ 70°pH ..... 7.0Calcium ..... 2,883Magnesium ..... 700Chlorides ..... 43,000Sulfates ..... 200Bicarbonates ..... 457Soluble Iron ..... 25

Remarks:

  
Respectfully submittedAnalyst: Eric Jacobson - Field Engineer

HALLIBURTON SERVICES

## NOTICE:

This report is for information only and the content is limited to the sample described. Halliburton makes no warranties, express or implied, as to the accuracy of the contents or results. Any user of this report agrees Halliburton shall not be liable for any loss or damage, regardless of cause, including any act or omission of Halliburton, resulting from the use hereof.