

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SEP - 8 1978

O. C. C.

ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
K-6772

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation	8. Farm or Lease Name Marlisue State
3. Address of Operator Box 848, Roswell, N.M. 88201	9. Well No. 1
4. Location of Well UNIT LETTER A, 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 14-S RANGE 29-E NMPM.	10. Field and Pool, or Wildcat Indesignates Queen Assoc.
15. Elevation (Show whether DF, RT, GR, etc.) 3836' GL	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as per verbal instruction as follows:

100' plug at total depth (2013)

100' plug 1015-1115 (base of salt)

100' plug 325-425 (8 5/8" csg. at 374')

15 sx plug at surface.

Heavy mud placed between plugs utilizing tubing.

Set dry hole marker.

Restore surface to as near its original condition as possible.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Call TITLE Operator DATE 9/06/78

APPROVED BY W. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE SEP 11 1978

CONDITIONS OF APPROVAL, IF ANY: