

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

NOV 16 1978

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1511
7. Unit Agreement Name
8. Farm or Lease Name M & M State
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Sk.
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator McClellan Oil Corporation ✓
3. Address of Operator P. O. Box 848, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER <u>L</u> , 1980 FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>15S</u> RANGE <u>29E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3747' G. L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

As per verbal instructions, will P & A as follows:

Bail hole dry and set 35sx plug at total depth; 35sx plug across Queen (1550'-1650'); 35sx plug in and out of 8 5/8" casing (324'); and 20 sx plug at surface. Set dry hole marker and restore surface as near as possible to its original condition.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe J. McClellan TITLE Operator DATE 11/15/78

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE NOV 17 1978

CONDITIONS OF APPROVAL, IF ANY: Intervals between plugs filled w/ mud