

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-2365

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rose Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Buffalo Valley Penn Gas

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18-15S-28E, NMPM

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR
Read & Stevens, Inc.

3. ADDRESS OF OPERATOR
P. O. Box 1518, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1650' FSL & 990' FEL Sec. 18, T-15-S, R-28-E, NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3565.2' GR - 3577' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 9200'. On 10-4-79, plugged and abandoned as follows:

1. Hole full of good mud, wt. 9.9#, Vis. 51, WL 10.2, pH 10.
2. Set 85 sx. cement plug 7225' - 7375'.
3. Set 60 sx. cement plug 5250' - 5350'.
4. Set 60 sx. cement plug 3170' - 3270'.
5. Set 50 sx. cement plug 1750' - 1850' across 8 5/8" casing shoe @ 1800'.
6. Did not cut and pull 8 5/8" casing.
7. Set 10 sx. cement plug 10' to surface.
8. Released rig @ 4:00 P.M., 10-4-79.
9. Installed regulation marker.
10. Will notify when location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AgentDATE 10-22-79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side