

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

RECEIVED

JUN 16 1983

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Marnel Pipe & Supply Co. ✓		5. State Oil & Gas Lease No. K 4321
3. Address of Operator P. O. Box 1037, Artesia, N.M. 88210		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>1</u> TOWNSHIP <u>15s</u> RANGE <u>29e</u> N.M.P.M.		8. Farm or Lease Name Alto State
		9. Well No. #1
		10. Field and Pool, or Wildcat Double L Queen Assoc.
15. Elevation (Show whether DF, RT, GR, etc.) 3873 gr.		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2007 PBDT 1987

Csg. 8 5/8" 340 - 225 sx circ.
4 1/2" 2007 - 500 sx circ.

Perfs. 1938-50

Propose to P & A as follows:

Spot a 25 sack cement plug at TD 1987 and tag.
Load hole with mud and spot a 25 sack cement plug at 450'
and a 10 sack surface plug with marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. [Signature] TITLE Consultant DATE 6-15-83

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 17 1983

CONDITIONS OF APPROVAL, IF ANY:

Notify NMACOG, by letter, of any change in status.

Plugging