

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
BEC Corporation

3. Address and Telephone No.
P.O. Box 1392 Midland, Texas 79702 915 682-1828

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
NE/4 NW/4 (660' FNL & 1980' FWL) Sec. 26 T-14-S R-29-E
Chaves, County, New Mexico

5. Lease Designation and Serial No.

NMM 25480

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Gulf Federal # 1

9. API Well No.

30-005-60738

10. Field and Pool, or Exploratory Area

19100 Double L Queen As

11. County or Parish, State

Chaves, New Mexico

12. **CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

APRIL 1997

- Plug & Abandonment PBTB 1924' Perf. 1824-36'
1. Set 45Sx Plug over Perforations 1920' to 1825'
2. Set 10Sx Plug from 1825' to 1759'
3. Tag Plug & Loaded Hole w/ Mud
4. Set 45Sx Plug from 403' to Surface
5. Removed all Production Equipment & Deadmen.
6. Set Well Marker.
7. Final Lease Clean-up.

Part ID-2
6-27-97
PVA



BUREAU OF LAND MGMT.
ROSWELL OFFICE

RECEIVED
1997 MAY 29 4:15 PM

14. I hereby certify that the foregoing is true and correct

Signed George V. Huser

Title Agent

Date 5-23-97

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____