

Form 9-3-81
(May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT INSTRUCTIONS ON REVERSE SIDE

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-14482

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

South Lucky Lake Fed.

9. WELL NO.

1

10. FIELD AND POOL, OR WHICAT

Undesignated

11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA

Sec. 15-15S-29E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Read & Stevens, Inc./

3. ADDRESS OF OPERATOR

P.O. Box 1518, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.
At surface

330' FSL & 330' FWL

DEC 14 1981

O. C. D.

ARTESIA, OFFICE

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)

3857' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Coring

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-5-81 Depth 1822'. Cored 1793'-1822', rec 29' of core. GIH again w/ core barrel.

12-6-81 Depth 1950'. Cored 1822'-1842', rec 20' of core. Went back in the hole w/DP & bit. TD well @ 1950'. Load the hole w/ KCL water, prep to run logs, loggers could not get below 1780'.

12-7-81 TD @ 1950'. GIH w/ DP & blow out water & fill. Load the hole w/ 10# mud, vis 5l, WL 9.6. POH w/ DP. Run FDC, CNL, MLL, DLL & GR. Start running 4 1/2" csg.

12-8-81 TD @ 1950'. Ran 48jts, total 1950', 4 1/2"-9.5# J-55 ST&C csg set @ 1950', FC @ 1909'. Cem w/ 400sx 50/50 poz mix Class "C" w/.3% Halad-4, 6# salt, circ 25sx. Cut off csg, set slips, WOC 18hrs. Move off Yucca Drlg Rig #4.

RECEIVED
DEC 09 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY

ROSWELL, NEW MEXICO

SIGNED ROGER A. CHAPMAN

(This space for Federal or State office use)

APPROVED BY DEC 11 1981
CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

TITLE Drilling & Production Mgmt DATE 12-8-81

TITLE

DATE

*See Instructions on Reverse Side