

CIS
9

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-005-62101
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WIW <input type="checkbox"/>	Lease Name or Unit Agreement Name Marlisue Queen Unit
Name of Operator M. E. W. Enterprise	Well No. 2-6
Address of Operator 300 S. Kentucky Ave., Roswell, NM 88201	Pool name or Wildcat Double L Queen
Well Location Unit Letter <u>F</u> : <u>1590</u> Feet From The <u>FNL</u> Line and <u>1870</u> Feet From The <u>FWL</u> Line	
24 Section 14S Township 29E Range NMPM Chaves County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify O.C.D. 24 Hrs. before start P&A operations.
2. MIRU. . NU BOP POH w/ tbg.
3. Set CIBP @ 1875 w/ 35 ft. cmt. on top.
4. RIH w/ tbg. circ. hole w/ 9.8 # mud.
5. POH to 1300 ft. spot 100 ft. cmt. plug (bottom of salt). *MIN. 25 x 1300' 1200' 105*
6. POH to 400 ft. spot 100 ft. plug (8 5/8 set @ 365 ft.) WOB & Tag *MIN. 25 x*
7. POH to 30 ft. circ. cmt to surface.
8. Cut off well head & install dry hole marker.



* Notice NMO.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks TITLE Agent DATE 06-26-00

TYPE OR PRINT NAME Wayne Brooks TELEPHONE NO. 915-580-7161

(This space for State Use)

APPROVED BY Trace Swellford TITLE Field Rep. II DATE 6/29/2000

CONDITIONS OF APPROVAL, IF ANY: