

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYNM OIL COM. COMMISSION
SUBMIT IN TRIPlicate
(Other instructions on re-
verse side)
Artesia, NM 88210Form approved.
Budget Bureau No. 42-R1424.

RECEIVED BY

FEB 25 1985

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. ☒ WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR

McClellan Oil Corporation ✓

3. ADDRESS OF OPERATOR

P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 660' FEL

5. LEASE DESIGNATION AND SERIAL NO.

NM-23540

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mark Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Double "I" South

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 25-T15S-R29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3883' G.L.

12. COUNTY OR PARISH

Chaves

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *


Propose to plug and abandon as per Peter Chester:

1. Set 1st plug at 1985' to 2085' with 25 sx Class C
2. Set 2nd plug at 400' to 500' with 25 sx Class C
3. Set 3rd plug at 0' to 50' with 25 sx Class C

Will tag plug #1 and place heavy mud between all plugs.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE

Operations Manager

DATE

2/14/85

(This space for Federal or State office use)

APPROVED BY

PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 25 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side