Form 3160-5			NN OIL COL	S. COMMISSION			e. c151	
(November 198 (Formerly 9-3	83) 331) DEI	UN STATES PARTMENT OF THE IN JREAU OF LAND MANA	Drewer DD TERIOR (Other	IN TRIPLICATE*	re-	Form approve Budget Burea Expires Augu	u No. 1004-0135	
·····,	В	JREAU OF LAND MANA	GEMENT VOISO	STde RECEIVED	5.	LEASE DESIGNATION		
		NOTICES AND REPOR		- <u></u>	6.	IF INDIAN, ALLOTT	EE OR TRIBE NAME	
(Do not u	use this form for pro	oposals to drill o	r to deepen o	r p149EB-25+88		-		
	ent reservoir. Use "	APPLICATION FOR PE	RMIT-" for su	ch proposals.)				
WELL		THER <u>Dry Hole</u>		O. C. D.		UNIT AGREEMENT NA	ME	
2. NAME OF OF	PERATOR	****				FARM OR LEASE NAM	Ε	
Read & Stevens, Inc.						Langley Federal		
3. ADDRESS OF OPERATOR						9. WELL NO.		
P.0. Box 1518, Roswell, NM 88201						4		
4. LOCATION OF WELL(Report location clearly and in accordance with State						10. FIELD AND POOL, OR WILDCAT		
requirements,* See also space 17 below,) At surface						Buffalo Valley Penn 11. SEC. T.,R.,M.,OR BLK. AND		
						SURVEY OR AREA		
1520' FNL & 1780' FEL						Sec. 14-T 155-R27E		
14. PERMIT NO		15. ELEVATIONS	(Show whether	DF,RT,GR,etc.)	.12	. COUNTY OR PARISH	The second s	
	-	3 · · · · · · · · · · · · · · · · · · ·	0' GL		}	Chaves	NM	
16.	Check Appro	opriate Box To Ind	icate Nature	of Notice, Report	t, Other	Data		
				,	• ··· • •	•·····		
	NOTICE OF INTEN	ITTON TO:			SUBSE	QUENT REPORT OF:		
TEST WATER		PULL OR ALTER CAS		WATER SHUT-O)FF	REPAIRIN		
FRACTURE T	· · · · · · · · · · · · · · · · · · ·	MULTIPLE COMPLETE		FRACTURE TRE		ALTERING		
SHOOT OR A		ABANDON*		SHOOTING OR				
REPAIR WEL	.L	CHANGE PLANS		(Other)				
(Other)				· · · · · · · · · · · · · · · · · · ·	rt resul	ts of multiple com	Dietion on Well	
				Completion	n or Rec	ompletion Report a	nd Log form.)	
	ROPOSED OR COMPLETED							
	date of starting any							
	/ertical depths for a 		nes pertinent	to this work.)*				
	Initial Hydrostatic	: 4331psi	2n	d Flow 65	5psi 6	Omins	Part IV-2	
	1st Flow	43psi 30m	ins Fi	nai 65	5psł		3-4-28	
	Final	65psi	2n	d SI 129	psi 12	0 mins	y'tH	
	1st SI	108psi 60m		drostatic 4310	•		1011	
	Rec'd 10' mud cut	FW, 1361 mud, sam	pler 55psi, 2	00cc mud, .489 cu	u ft gas.	• Set plugs as		
	follows:		•					
Spot 45sx Class "H" cmt 83961-82501 Spot 45sx Class "H" cmt 64461-63001 Class "H" "H								
Spot 35sx Class "C" cmt 4396'-4300' Spot 35sx Class "C" cmt 17 Wait 4hrs to tag cmt.						7711-1675	谷入	
	Hall Hars to lag ch	nr •			st ^{re}	•	<u>, ≪</u> .\	
10-13-85	Release rig @ 7:00p	om 10-12-85, Tagge	1 oluc @ 1650	1. Spotted 35sx C	lass no	" cmt 440-150",		
	spotted 15sx Class	÷ -	· •	-				
			,	•		E. 10 4		
10-14-85	RD Sierra Rig #2.				Ν.	Toos		
					l - L			
10-15-85	Move rig off locati	on. Clean locatio	n. Will notif	y when location r	eady for	Inspection		
1 hereby cer	tify that the forego	ing is true and c						
	1 Ant							
SIGNED (O Statt	3	TITLE Dril	ling & Production	Manager	r DATE 10-	- 15-85	
(This spac	e for Federal or Sta	ite office use)		······································				
· · ·					1	APPROV	/ED I	
APPROVED B		·	TITLE			PEPER W CI	IESTER	
WNDTETONS	OF APPROVAL, IF AND	*See Tr	nstructions o	n Reverse Side				
						JAN % 5	1988	
						BUREAU OF LAND	MANAGEMENT	
						DUREAU OF CHILD	OCE AREA	