State of New Mexico Minerals and Natural Resources Department Ene

OIL CONOR

CISI	Form C-103 Revised 1-1-89
w 4.165	

P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION 2040 Pacheco St.					
		WELL API NO.	_ , _ , _ ,	,	
DISTRICT II Santa Fe, NM 87505 P.O. Drawer DD, Artesia, NM 88210			5-62531	·	
		sindicate Type of Lea			
DISTRICT III		01-1-01-1	STATE	FEE	
1000 Rlo Brazos Rd., Aztec, NM 87410			₅State Oil & Gas Leas	se No.	
SLINDRY NOTI	CES AND PEDODES OF	NI MELLO			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Land Name and Name and Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7-Lease Name or Unit Agreement Name Marlisue Queen Unit			
	-101) FOR SUCH PROPOSAL	5.)	ivianisae queen	Offic	
Type of Well: OIL GAS					
WELL OTHER WIW		101 1101			
2Name of Operator M. E. W. Enterprise		sWell No. 2-8			
3Address of Operator		«Pool name or Wildcat			
300 S. Kentucky Ave., Roswell, NM 88201		Double L Queer			
4Well Location					~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Unit Letter F : 2140	Feet From The FNL	Line and 2475	Feet From The	FWL	Line
24 - 442		_			
24 Section 14S	Township 298		NMPM	Chaves co	unty
	inclevation (Show whe	ether DF, RKB, RT, GR, etc.)			
11 Check An					
		ate Nature of Notice, Re	port, or Other D)ata	
NOTICE OF INTENTION TO: SUBSEQUENT RI			SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				<u></u>	
		Z. REIVEDIAL WORK	닏	ALTERING CASING	L
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING O	PNS.	PLUG AND ANBANDO	NMENT
PULL OR ALTER CASING		CASING TEST AND CEME	CASING TEST AND CEMENT JOB		
OTHER:		OTUED.	OTUE D		
OTTER.		OTHER:			
12Describe Proposed or Completed Operations	; (Clearly state all pertinent details,	and give pertinent dates, including es	timated date of starting	any proposed	 -
work) SEE RULE 1103.	D0.4				
 Notify O.C.D. 24 Hrs. before start MIRU. NU BOP POH w/ tbg. 	P&A operations.				
3. Set CIBP @ 1875 w/ 35 ft. cmt. o	n top.			26270	
4. RIH w/ tbg. circ. hole w/ 9.8 # ms	id. Cut & pull 4 1/2 csg. +- 1	1300 ft.	242	5202128203	
75. POH to 1300 ft. spot 100 ft. cmt.	plug (bottome of salt).	T 4 M '4 3C 45 50	701 /35	5262728 2930 E	
75. POH to 1300 ft. spot 100 ft. cmt. plug (bottome of salt). 6. POH to 450 ft. spot 100 ft. plug (8 5/8 set @ 393 ft.) WOC & Tag X M, N, 25 5X cement. Plus, 100 ft. circ. cmt to surface.					
8. Cut off well head & install dry hole marker.					
1			20 20	RECEIVED	ン ン
Set 25 TX Cement Plus 1300- 1200- 1200- TAG					<u>s</u> /
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					
			19,	رم ^۷ /	
			3/1	PERTUROL	
.	,	_		GLOV	
For the 1300 ft. spot 100 ft. cmt. plug (bottome of sait). 6. POH to 450 ft. spot 100 ft. plug (8 5/8 set @ 393 ft.) WOC & Tag x Min. 25 sx cement. Plug. 7. POH to 30 ft. circ. cmt to surface. 8. Cut off well head & install dry hole marker. Set 25 sx cement Plug 1300-1200-1200-1200 X Notific NMO(D. To witness Plugging Operations. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
I hereby certify that the information above is t	rue and complete to the best of my	knowledge and belief.			
SIGNATURE Was 1	3 40	TITLE Agent		DATE 06-26-00	
TYPE OR PRINT NAME Wayne Brooks			-	TELEPHONE NO. 915-58	30-7161
(This space for State Use)					

TITLE Field Rep. I DATE 6/29/2000.

APPROVED BY Mile Still CONDITIONS OF APPROVAL, IF ANY: