Submit 3 Copies to Appropriate District Office

State of New Mexico Ene. , Minerals and Natural Resources Department

CIST	Form C-103 Revised 1-1-89	-
V		

TELEPHONE NO. 505/748-1471

District Supervisor

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe, New Mexico 87504-2088

VELL	API NO.
	30-00

	30-005-6322	23
5.	Indicate Type of Lease	CZZ

dicate	Туре	of	Lease	GT)		Г
	••		STATE	X	FEE	L

P.O. Drawer DD, Artesia, NM 88210	252627	STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	4	6. State Oil & Gas Lease No. V-4459		
SUNDRY NOTICES AND REPORTS ON WEL	LS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PEI (FORM C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
1. Type of Well: OR. OAS WELL X OTHER	-014 S	Windmill ATI State		
2. Name of Operator /	15	8. Well No.		
YATES PETROLEUM CORPORATION	Certions,	1		
3. Address of Operator		9. Pool name or Wildcat		
105 South 4th St., Artesia, NM 88210		Wildcat Morrow		
4. Well Location	1650	. Fact		
Unit Letter J :1650 Feet From The South	Line and 1030	Peet From The East Line		
Section 16 Township 15S Ra	inge 28E	NMPM Chaves County		
Section 16 Township 15S Ra	DF, RKB, RT, GR, etc.)	V/////////////////////////////////////		
3562				
11. Check Appropriate Box to Indicate 1	Nature of Notice, Re	eport, or Other Data		
NOTICE OF INTENTION TO:		SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING	CASING TEST AND CE	MENT JOB		
OTHER:		ion casing & cement X		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, as work) SEE RULE 1103. TD 9320'. Reached TD at 10:00 PM 10-15-99. as follows: 25 joints of 5-1/2" 17# N-80 8r J-55 8rd LT&C (416.91'); 14 joints of 5-1/2' 5-1/2" 17# J-55 8rd ST&C (788.81'); 122 joint 31 joints of 5-1/2" 17# J-55 8rd LT&C (1337. Float shoe set at 9320'. Float collar set a marker set at 7688'. Pumped 500 gallons of H, 5/10% Halad 344, .4% CFR3, 5#/sack gilson PD 10:15 PM 10-17-99. WOC. NOTE: Displace 2:15 AM 10-18-99. Waiting on completion unit.	Ran 221 joints of LT&C (1040.90 ' 17# N-80 8rd Lats of 5-1/2" 17.05') (Total 933 at 9277'. Botto mud flush ahead hite and 1# salted casing with 2	of 5-1/2" 17# & 15.5# casing '); 10 joints of 5-1/2" 17# T&C (571.71'); 19 joints of # J-55 8rd LT&C (5179.29') and 4.13') of casing set at 9320'. m marker set at 7818'. Top of 630 sacks Super Modified (yield 1.66, weight 13.0).		
$\mathcal{K} = \mathcal{K}(a)$	Operations To	echnician DATE Oct. 26, 1999		
SIGNATURE 7 WALL THE	LB	PAID -		
Rusty Klein		TELEPHONE NO. 505/748-1		

CONDITIONS OF APPROVAL, IF ANY:

(This space for State Use)

AFFROVED BY-