

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

CISF
80

Form C-103
Revised March 25, 1999

WELL API NO.

30-005-63313

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

V-4459

7. Lease Name or Unit Agreement Name:

Windmill ATI State

7. Well No.

#4

8. Pool name or Wildcat

Buffalo Valley Penn

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter **L** : **1650** feet from the **South** line and **660** feet from the **West** line

Section **16** Township **15S** Range **28E** NMPM **Chaves** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3570' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/11/01 - Drilled to 9977'. Run open hole logs. Logger's TD 9979'.

1/12/01 - Drilled to 10,167'. Reached TD at 10:30 AM. Wait on orders.

Decision to plug and abandon. Jim Krogman received verbal P&A instructions from Mike Stubblefield with OCD at 4:30 PM.

1/13/01 - Set cement plugs as follows:

Plug #1 - 10,167' - 30 sxs H

Plug #2 - 8920' - 35 sxs H

Plug #3 - 5380' - 35 sxs H

Plug #4 - 3290' - 35 sxs H

Plug #5 - 1900' - 80 sxs H + 4% CaCl₂. WOC 4 hours. TIH and tagged cement at 1750'.

1/14/01 - Plug #6 - 450' - 25 sxs H

Plug #7 - 10 sxs surface plug.

Rig released at 11:00 AM.

WELL IS PLUGGED AND ABANDONED

1/18/01 - Installed regulation dry hole marker and fenced front of pits.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Susan Helgerson* TITLE Engineering Technician DATE April 2, 2002

Type or print name Susan Helgerson Telephone No. 505-748-1471

(This space for State use)

APPROVED BY *Field Rep ID* TITLE DATE APR 23 2002

Conditions of approval, if any: