

13. Operator's Representatives and Certification


The field representative responsible for assuring compliance with the approved surface use and operations plan are as follows:

Gene Simer
District Operations Manager
309 S. Halagueno Street
Carlsbad, NM 88220
Office: (505) 885-1313
Mobile: (505) 390-3722

Alan McNally
District Engineering Manager
14000 Quail Springs Parkway, Suite 600
Oklahoma City, OK 73134
Office: (405) 749-5277
Mobile: (405) 590-2449

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; that the work associated with the operations proposed herein will be performed by Dominion Oklahoma Texas Exploration & Production, Inc. and its contractors and sub-contractors in conformity with this plan and the terms and conditions under which it is approved.

Date


11/30/01

Alan C. McNally
District Engineering Manager
Dominion Oklahoma Texas
Exploration & Production, Inc.