

115-23-71
sent C-103 R. A. Agent
C-105

March 13, 1964

Wilbur E. McMurtry
Consulting Geologist
City National Bank Bldg.
105 N. Broadway
Oklahoma City 2, Oklahoma

Re: M. S. Thompson,
Morris Estate, Well #1,
14-17-25, Eddy County,
New Mexico.

Dear Mr. McMurtry:

In answer to your letter of March 11, 1964, I believe the M. S. Thompson well you are referring to is in section 14-17-25, as we have no other well drilled by Thompson. No, we don't require the surface pipe be left in the hole, but in this particular area the surface pipe has to be circulated to surface. This well has 1176' of 7" pipe left in the hole with 529 sacks of cement behind.

Yours very truly,

OIL CONSERVATION COMMISSION

M. L. Armstrong

MLA/uh

March 13, 1964

William B. Montgomery
Community Association
City National Bank Bldg
105 N. Broadway
Oklahoma City, Oklahoma

Mr. B. J. Thompson
Municipal Water Dept
14-17-25, Tulsa County
New Mexico

Dear Mr. Montgomery:

In answer to your letter of March 11, 1964, I believe
the Y. B. Thompson well you are referring to is in section
14-17-25, as was the well drilled by Thompson.
No, we don't replace the surface pipe as laid in the hole,
but in this particular area the surface pipe has to be
circumfered to surface. This well has 18" of 7" pipe left
in the hole with 50' more of cement below.

Yours very truly

JOHN CONSERVATION COMMISSION

M. J. Thompson

M. J. Thompson