

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501 MAR 4 '83

Form C-103
Revised 10-1

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Gissler "AV"
3. Address of Operator 207 S. 4th Street; Artesia, N.M. 88210	9. Well No. 2
4. Location of Well UNIT LETTER B, 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 17S RANGE 25E N.M.P.M.	10. Field and Pool, or Wildcat San Eagle Creek, Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3482 GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP at 1250' KB and place 15-sx (100' min) cement plug over CIBP*

Set 15-sx (100' min) cement plug to equally cover top of San Andres at 696'.

Set 10-sx cement plug at surface and install dry hole marker.

Restore surface and notify NMOCD for final inspection.

NOTE: Well sketch attached.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James S. Brown TITLE Engineer DATE 3-4-83

APPROVED BY Larry Brooks TITLE Geologist DATE 3/4/83

CONDITIONS OF APPROVAL, IF ANY: * Tag plug to see if BP & plug holding
Notify N.M.O.C.C. in sufficient time to witness