

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD

RECEIVED

Shot	Shot used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
						DEC 20 1976
						O. C. C.
						ARTESIAN OFFICE

TOOLS USED

Rotary tools were used from _____ spudding _____ feet to _____ feet, and from _____ feet to _____ feet
 Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet

DATES

_____, 19____, Put to producing _____ dry & abandoned _____, 19____

The production for the first 24 hours was _____ barrels of fluid of which _____ % was oil; _____ %
 emulsion; _____ % water; and _____ % sediment. Gravity, °Bé _____

If gas well, cu. ft. per 24 hours _____ (Gallons gasoline per 1,000 cu. ft. of gas _____)

Rock pressure, lbs. per sq. in. _____

EMPLOYEES

_____, Driller _____ W. D. Cunningham (Contractor) Driller
 _____, Driller _____, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
-------	-----	------------	-----------

The following below is taken from the scout account there was no logs, etc.

March 25, 1942 Total depth 895' lime. Shut down for orders. Temporarily abandoned.

Spudded in February 7, 1942.

2-18-42 Digging up on location.
 2-25-42 Drilling @ 355' anhydrite. Show water 155' red beds
 3-4-42 Total depth 605' red sand. Shut down repairs. 1 Barrel water per hour @
 264-270' in anhydrite. 4 bbls sulphur water per hour @ 365-372' in anhydrite
 and brown lime.
 3-11-42 Drilling 660' anhydrite in salty sulphur water 593-605' in sand. Slight
 show gas 645-650 in brown lime.
 3-18-42 Drilling 795' lime, anhy & red beds.

Temporary abandoned March 20, 1942.