

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other instr
verse side)

BY HAND

Form approved,
Budget Bureau No. 42-R-104
5. LEASE DESIGNATION AND SERIAL NO.

L 2 062618

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <i>Continental Oil Company</i>	8. FARM OR LEASE NAME <i>G.W. Duffield</i>
3. ADDRESS OF OPERATOR <i>Box 460, Hobbs, New Mexico 88240</i>	9. WELL NO. <i>1</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1980' FSL and 1980' FWL, Section 21, T-16, R-27, Eddy County, New Mexico</i>	10. FIELD AND TOLL OR WILDCAT <i>Duffield</i> <i>Perm. Sec. Pool</i>
14. FURNISH	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec. 21, T-16, R-27</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Eddy</i>
	13. STATE <i>NM</i>

RECEIVED

SEP 4 1968

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

☒ TEST WATER SHUT-OFF
☒ ARTESIAN DEFICIT TREAT
☐ EJECT OR ACIDIZE
☐ REPAIR WELL
☐ (Other)

☐ PULL OR ALTER CASING
☐ MULTIPLE COMPLETE
☐ ABANDON*
☐ CHANGE PLANS

SUBSEQUENT REPORT OF:

☐ WATER SHUT-OFF
☐ FRACTURE TREATMENT
☐ SHOOTING OR ACIDIZING
☐ (Other)

☐ REPAIRING WELL
☐ ALTERING CASING
☒ ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The well was plugged and abandoned by the procedure shown below.

Found packer at 8508 and hold-down at 8495. Cut tubing at 8485 and pulled same (2 1/2" OD). Set 50 sacks Neat cement 8485-8170. Cut 7" casing at 3020 and pulled same. Set 50 sack cement 3030-2900, 25 sacks 1380-1320 and 10 sacks at surface. Erected dry hole marker 11-18-67.

USGS-5 file

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Gault

TITLE

Adm. Sec. Chief

(This space for Federal or State office use)

DATE

8-23-68

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*Stat Book Shows 4, 421, 688 MCF
15, 761 BO*

DATE

*See Instructions on Reverse Side