Submit 3 Copies to Appropriate District Office	State of Ne Energ, ∩erals and Natu		kico sources Department	0181	Form C-1 Revised 1		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 2040 Pacheco St. Santa Fe, NM 87505				WELL API NO. 30 -	015-005	72	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210				sIndicate Type of Lease			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				STATE X FEE			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				√Lease Name or Unit Agreement Name Hitchcock - 27			
Type of Well:							
2Name of Operator Marbob Energy Corporation	ame of Operator				eWell No.		
3Address of Operator				⊮Pool name or Wildcat Dog CanyonD			
P.O. Box 227, Artesia, N M 88210 4Well Location							
Unit Letter _ D :660	Feet From The North		Line and 660	Feet From The	west	_ Line	
Section 27	Township 16S		tange 27E	NMPM	Eddy c	County	
	<sup>10</sup> Elevation ( <i>Show wheth</i> 3497GR	ner DF, I	RКВ, R1, GR, etc.)				
<sup>11</sup> Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK	PLUG AND ABANDON	$\mathbf{X}$	REMEDIAL WORK		ALTERING CASING	;	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING O	PNS.	PLUG AND ANBANI	ONMENT	
PULL OR ALTER CASING			CASING TEST AND CEMI	ENT JOB			
OTHER:			OTHER:			[]	
<ul> <li>Describe Proposed or Completed Operations work) SEE RULE 1103.</li> <li>Notify OCD 24 Hrs. before starting 1. POH W/ rods &amp; tubing 2. Set CIBP @1350 w/ 35' cmt. 0 3.Circulate hole w/mud 4.Sopt 100' cmt. @ 1100 5.Spot 30' plug @ surface 6. Cut off well head install dry ho</li> </ul>	a on top	and give	pertinent dates, including es	timated date of starting	any proposed	·*	
See (	2Hachel	(knowledge)	dae and belief		RECEIVED OCD - ARTES		
SIGNATURE					DATE 12-10-0	)1	
TYPE OR PRINT NAME Wayne Brooks					TELEPHONE NO. 915	5807161	
(This seess for State Lioo)	cord only	<u></u> т	TLE		date 12-	21-01	

,

Operator MARbob Emgy Parp Well <u>Hitchrock</u> 27 Unit <u>D</u> Section <u>7</u> Township <u>16</u> Range <u>2</u> API# 30-015 -- 00572 60' Labor Play • • the plug 103-208-8518 • 158' Cuic 1100' 6 CIBP W 35 Uben -1 350' 1405 1407 51/2 1411' Cize

- TOPS				
alt				
B. Salt				
Yates				
Glorieta				
Delaware				
Bone Sp.				
Abo				
Wolfcamp				
Morrow				
Devonian				
Fusselman				
Other (16400 1683)				
SA 1108				

- Contact OCD 24 hrs. prior to any work done.
- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install dry hole marker as per rule 202.B.2
- Plugs are to be set from point indicated up. Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- Surface plug will be from 0'- 60'
- Where plugs are required cement must be placed inside and outside of all casing string(s), in the correct footage or sacks required, if no cement exists.
- Plugs to be tagged will be indicated.

\* This would be the suggested Par. Borrise From the state, howour the Blunch Mugd approve the Pit A Account.