

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE
(Other instructions on reverse side)

Form approved
Budget Item # 15.00000
Request Approved

5. LEASE NUMBER (If applicable)
NM-0557370

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use APPLICATION FOR PERMIT-- for such proposals.)

1. NAME OF OPERATOR Mark Energy Corporation	7. UNIT IDENTIFICATION NO.
2. ADDRESS OF OPERATOR P.O. Drawer 217, Artesia, N.M. 88210	8. FARM OR EXCESS LAND Hondo
3. NAME OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) 330 FSL 990 FWL	9. WELL NO. 1
10. FIELD AND BLOCK OR WELLS Red Lake On Grbg SA	11. SEC., T., R., N., OR BLM, AND SURVEY OR AREA Sec. 26-T17S-R27E
12. COUNTY OR PARISH (If other) Edgy	13. STATE N.M.

RECEIVED
MAY 15 '89
C. C. D.
ARTESIA OFFICE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TRIP	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
REPAIR	<input type="checkbox"/>	FRAC TREATMENT	<input type="checkbox"/>
DRILL	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
RECOMPLETION	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
WELL OR ALTER CASING	<input type="checkbox"/>	(NOTE: Report results of multiple completions on a Completion or Recompletion Report and not on this form.)	
MULTIPLE COMPLETE	<input type="checkbox"/>		
ABANDON*	<input checked="" type="checkbox"/>		
CHANGE PLANS	<input type="checkbox"/>		

7. DESCRIBE THE NATURE OF REPORTED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated dates of completion of reported work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and locations pertinent to the well.)

We propose to plug & abandon as follows:

Set a cmt plug from TD to 1500' (tag), set cmt plug from 1330' - 4200' - 1000' (tag), set cmt plug from 670' - 570' across surface shoe, 50' surface plug, install dry hole marker and clean location.

APR 14 11 05 AM '89
CANTON AREA

RECEIVED

Prepared by: Rhonda Nelson TITLE Production Clerk DATE 4/13/89

Checked by: Sham... FOR: ... DATE 5 12 89

*See Instructions on Reverse Side