

ckf

Formerly 9-331

DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) BUREAU OF LAND MANAGEMENT

LEASE DESIGNATION AND SERIAL NO.

LC-057798

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

0. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Magruder A

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Empire (Yates-Seven Rivers)

11. SEC., T., R., W., OR BLK. AND SURVEY OR AREA

Sec. 35-T17S-R27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

OIL WELL GAS WELL OTHER

NAME OF OPERATOR Cities Service Oil and Gas Corporation ✓

ADDRESS OF OPERATOR P.O. Box 1919 - Midland, Texas 79702

RECEIVED BY APR 23 1986 D. C. D. ALBUQUERQUE OFFICE

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface

1650'FSL & 1650'FEL

PERMIT NO. 30-015-00625

15. ELEVATIONS (Show whether DF, W, OR, C, etc.) N/A

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF, FRACTURE TREAT, SHOOT OR ACIDIZE, REPAIR WELL, (Other), FULL OR ALTER CASING, MULTIPLE COMPLETE, ABANDON*, CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF, FRACTURE TREATMENT, SHOOTING OR ACIDIZING, (Other), REPAIRING WELL, ALTERING CASING, ABANDONMENT* (X)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

O.T.D. 465' Lime. This well was plugged and abandoned in the following manner:

- 1. MIRU a pulling unit and POOH w/rods, BHP and tubing. RIH w/OE'd tubing to O.T.D. 465' and pumped a 50 sack Class C Neat cement plug @ 465 - 410'. POOH w/tubing and WOC for 12 hrs.
2. RIH w/OE'd tubing and tagged plug @ 410'. Mixed and pumped a 150 sack Class C Neat cement plug @ 410 - surface. POOH w/tubing and cut off WH.
3. Installed a 4" dry hole marker to designate a plugged and abandoned location.

BLM located at Carlsbad, New Mexico witnessed the plugging of this well.

I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Reg. Opr. Mgr. - Prod.

DATE 4-21-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post FD-2 5-2-86 PVA