Well Unit	Prons hern Mant. Corp.  Conscion 36 Twiship 17	Range <u>7</u> 7	TOPS
API#	30-0 15- 00666		LIGITOS 277.
	+ 60' Surface Plug.		
	·		
		Salt gel mud co of gel per barre plug. Install dry hole Plugs are to be Plugs must not of cement, whice specifically indice Shoe and stub shoe or stub and Surface plug wi Where plugs ar placed inside and in the correct for cement exists. Plugs to be tage	plugs will be 50' above and below d tagged.  Il be from 0' - 60' e required, cement must be nd outside of all casing string(s) otage or sacks required, if no
(al. Toc - 372"	← 372'. Cement Plug Inside +	outsile 51/2	"esg. TAG
5112" @ Sci	← 533"- 451". TAG		
ZC SXS			