

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	✓
PILLS	✓
U.S.G.S.	✓
LAND OFFICE	✓
OPERATOR	✓

RECEIVED BY
SEP - 2 1986
O. C. D.

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
B8318

SUNDRY NOTICES OF ARTESIAN OFFICES ON WELLS
DO NOT USE THIS FORM FOR PROPOSAL OF WORK OR FOR RETURN OF PROPOSAL TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSAL.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Blue Sky Production	8. Farm or Lease Name Acery Acery
3. Address of Operator P. O. Box 1772 Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT CATER F 2310 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 17S RANGE 27E	10. Field and Pool, or Wildcat Empire (V-SR)
11. Elevation (Show whether DF, KT, CR, etc.) 3620 AC	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run tubing to 340'.
2. Spotted 125 sacks of cement.
3. Tagged @ 240'.
4. Pumped 135 sacks from surface.
5. Tagged @ 80'.
6. Spotted 35 sacks of cement.
7. Tagged @ 10'.
8. Spotted 10 sacks to surface.
9. Install P & A Marker.

Post ID 2
9-5 86
P & A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale May TITLE Plug and Abandon Supervisor DATE 8-28-86

APPROVED BY Danell Moore TITLE Geologist DATE 10/1/86

CONDITIONS OF APPROVAL, IF ANY: