State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-015-01218
DISTRICT III		2000	5. Indicate Type of Lease STATE X FEE
1000 Rio Brizos Rd., Aziec, NM 87410			6. State Oil & Gus Lance No. B-752
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
I. Type of Well: OL GAS WELL XX WELL	Other	RECEIVED	
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·	12'00	EMPIRE ABO UNIT "H"
ARCO OIL AND GAS COMP	ANY V	MAY 17 '90	8. Well No. 18
BOX 1710, HOBBS, NM	99370	O. a., D.	9. Pool same or Wildox
4. Well Location		ARTESIA, OFFICE	EMPIRE ABO
Unit Letter N: 330	Feet Prom The SOUTH	Line and 231	O Feet From The WEST Line
Section 36	Township 17S R	27E	NMPM EDDY County
	10. Elevation (Show whether 3644 KB	DF, RKB, RT, GR, etc.)	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	ALTERING CASING
PULL OR ALTER CASING			
OTHER:		CASING TEST AND CEMENT JOB	
		OTHER: TEMPORAL	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of marting any proposed work) SEE RULE 1103. TD 5925', PBD 5885', PERFS 5725-5750'			
TA & HOLD WELL BORE FOR FIELD BLOW DOWN			
	BOP. Work on unseating packer.		
5/9/90 R.O. Continu	/90 R.O. Continue to work on pkr. POH w/tbg & pkr. Pkr had parted in Mandrel. RIH w/bit & scrapper. Tagged up at 5843.46'.		
5/10/90 R.O. RIH w/t Attempted to & tbg. Tag (5/10/90 R.O. RIH w/tbg & CIBP. Set CIBP. POH w/l jt tbg. Circ. hole. Close csg. Attempted to press. up, would not hold press. POH w/tbg. RIH w/Model R pkr & tbg. Tag CIBP. Pull up arrpox. 10'. Tried to press. up on CIBP. Would not hold. Unset pkr. POH w/tbg & packer. SDON.		
5/11/90 R.O. RIH w/CIBP & tbg. Set CIBP. Circ. well. Close well in. Press. up to 500#. Held for 15 min. POH w/tbg & CIBP running tool. Tbg layed down in singles. First CIBP appeared to be set in top perfs of well and tally confirmation on POH. Second CIBP ran & set at 5701'.			
Pressure Fest witnessed by Gary Williams, NMOCD. Chart attached.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Manual Administrative Supervisor DATE 5/17/90			
TYPEOR PROTECTION James D. Cog	burn		ТВЕРНОНЕ NO. 392—3551
(This space for State Und)			
ATROVED BY THE DIL AND GAS INSPECTOR DATE 7-10-90			
WARRING WINNING F MIL			

